

Harness Repair Connector 2 Pin Kit 10pc



Additional Information

- Ford ignition coil connector.
- Kit contains: 2 x 2 Pin female connectors, 4 x Red weatherproof seals (Part No. 37360), 4 x terminals which suits 0.75mm 1.5mm² (Part No. 37355).
- 10pc.
- · Supplied in a blister.
- Included in assorted connector & harness repair kit, Part No. 37340.

http:///product/37348











