

Heat Shield Repair Kit - 10pc

Exhaust under body heat shields have an annoying habit of failing around the area of their fixing point leading to rattling noises. The heat shields are usually still serviceable but their mounting holes will have become too big for the clamping washers to fix them in place. The Connect 34316 kit provides a 52mm diameter disc of heat shield material and a clamping washer to allow the original shield to be repaired and reused.



Additional Information

- Applications include: Ford & Volkswagen Group vehicles.
- Kit contains: 5x heat shield discs, 5x heat shield washers.
- For fitting tool please see Laser Part No. 7347.
- Assorted heat shield fastener kits also available, please see Connect Part No. 30286.
- Top heat shield discs also available separately, please see Part No. 34317 - pack of 20pc.

<http://product/34316>

Video available: <https://youtube.com/shorts/fmCH4aesIM4>

