

## Joint d'étanchéité pour la réparation de faisceaux



### Additional Information

- Convient pour les câbles de 0.5mm - 0.75mm<sup>2</sup>
- Utilisation sur les faisceaux et les capteurs VW
- Joint d'étanchéité pour les kits de réparation : 37341,37342,37343,37347,37349.
- Joint d'étanchéité bleu
- Blister de 100 pcs

<http://product/37358>



**Replacement Part No. 37478**

**ASSOCIATED PRODUCTS**

**37423 2-pin Alternator / Universal Applications Connector**

ALSO USED WITH SENSOR PART NOS:  
37424  
37431  
37441

**37358 Weather Seal**





**Replacement Part No. 37480**

**ASSOCIATED PRODUCTS**

**37428 2-pin Crank Angle Sensor Connector**

ALSO USED WITH SENSOR PART NOS:  
37587  
37597

**37358 Weather Seal**





**Replacement Part No. 37353**

**ASSOCIATED PRODUCTS**

**37586 4-pin Ignition Coil Connector**

ALSO USED WITH SENSOR PART NOS:  
37587  
37597

**37358 Weather Seal**





**Replacement Part No. 37353**

**ASSOCIATED PRODUCTS**

**37586 3-pin Camshaft Sensor Connector**

ALSO USED WITH SENSOR PART NOS:  
37587  
37597

**37358 Weather Seal**





**Replacement Part No. 37600**

**ASSOCIATED PRODUCTS**

**37599 4-pin Air Pressure Sensor Connector**

**37358 Weather Seal**





**Replacement Part No. 37602**

**ASSOCIATED PRODUCTS**

**37605 2-pin Multi-Purpose Ignition, ETC & Coolant Connector**

ALSO USED WITH SENSOR PART NO:  
37607

**37358 Weather Seal**



